General Purpose Jobber Length Parabolic Flute Drills

Styles

QC21P, QC21G

How To Use This Chart:

1.Determine your Workpiece Material from the Application Material Groups (AMG) below.

2.Use the Icons to find Product Features.

3.Find the Surface Feet Per Minute (SFM) and Alpha Code

example: 361W

361 = SFM

W = Alpha Code used to find your Feed Rate

	HSS	HSS
	ANSI	ANSI
	4XD	4XD
	135°	135°
		TiN
		
	QC21P	QC21G
	1/16 - 11/16	1/16 - 1/2
	102	102
1.1	98F	115F
1.2	59F	69F
1.3	66H	75H
1.4	59F	69F
1.5	46D	56D
1.6		
1.7		
1.8		
2.1	89H	105H
2.2	49F	59F
2.3	49D	59D
2.4		
3.1	151H	171H
3.2	79H	89H
3.3	79F	95F
3.4		59D
4.1	89H	
4.2	49F	
4.3		
5.1	49F	59H
5.2		
5.3		
6.1	89I	98I
6.2	79H	89H
6.3	79H	89H
6.4		
7.1	351H	400H
7.2	325H	351H
7.3		
7.4	276H	315H
8.1		
8.2		
8.3		
9.1		
10.1		

Feed Rate Chart

Alpha Code	Feed in Inches per Revolution (IPR) ± 25% — Ø Diameter															
	1mm/ 1/32"	2mm/ 3/32"	3mm/ 1/8"	4mm/ 5/32"	5mm/ 3/16"	6mm/ 1/4"	8mm/ 5/16"	10mm/ 3/8"	12mm/ 1/2"	15mm/ 9/16"	16mm/ 5/8"	20mm/ 3/4"	25mm/ 1"	30mm/ 1.1/8"	40mm/ 1.5/8"	50mm/ 2"
A	0.0004	0.0009	0.0011	0.0013	0.0014	0.0017	0.0021	0.0024	0.0027	0.0032	0.0034	0.0043	0.0049	0.0053	0.0061	0.0069
B	0.0006	0.0011	0.0015	0.0016	0.0018	0.0021	0.0026	0.0031	0.0035	0.0041	0.0043	0.0053	0.0060	0.0065	0.0074	0.0082
C	0.0006	0.0013	0.0017	0.0020	0.0022	0.0025	0.0031	0.0039	0.0043	0.0049	0.0051	0.0063	0.0071	0.0077	0.0087	0.0094
D	0.0006	0.0015	0.0021	0.0024	0.0027	0.0031	0.0039	0.0047	0.0051	0.0059	0.0061	0.0074	0.0083	0.0090	0.0100	0.0108
E	0.0007	0.0017	0.0024	0.0028	0.0031	0.0037	0.0045	0.0055	0.0059	0.0068	0.0071	0.0085	0.0094	0.0102	0.0112	0.0122
F	0.0007	0.0020	0.0029	0.0033	0.0037	0.0043	0.0054	0.0065	0.0070	0.0080	0.0083	0.0098	0.0108	0.0116	0.0126	0.0135
G	0.0007	0.0022	0.0033	0.0038	0.0043	0.0050	0.0063	0.0075	0.0081	0.0091	0.0094	0.0110	0.0122	0.0130	0.0140	0.0148
H	0.0008	0.0026	0.0040	0.0046	0.0051	0.0059	0.0075	0.0090	0.0096	0.0107	0.0110	0.0126	0.0140	0.0148	0.0157	0.0165
I	0.0008	0.0030	0.0047	0.0053	0.0059	0.0068	0.0087	0.0104	0.0110	0.0122	0.0126	0.0142	0.0157	0.0165	0.0173	0.0181
J	0.0009	0.0033	0.0053	0.0060	0.0067	0.0078	0.0098	0.0117	0.0124	0.0137	0.0142	0.0159	0.0175	0.0183	0.0191	0.0198
K	0.0010	0.0036	0.0059	0.0067	0.0075	0.0087	0.0110	0.0130	0.0138	0.0153	0.0157	0.0177	0.0193	0.0201	0.0209	0.0215
L	0.0011	0.0040	0.0065	0.0073	0.0082	0.0094	0.0120	0.0142	0.0152	0.0165	0.0169	0.0191	0.0207	0.0215	0.0224	0.0231
M	0.0012	0.0043	0.0071	0.0080	0.0089	0.0102	0.0130	0.0154	0.0165	0.0177	0.0181	0.0205	0.0220	0.0228	0.0238	0.0248
N	0.0013	0.0047	0.0077	0.0086	0.0095	0.0110	0.0140	0.0165	0.0179	0.0189	0.0193	0.0219	0.0234	0.0242	0.0253	0.0265
S	0.0003	0.0006	0.0008	0.0010	0.0012	0.0015	0.0020	0.0031	0.0039	0.0048	0.0051	0.0059	0.0070	0.0070	0.0090	
T	0.0006	0.0011	0.0016	0.0020	0.0024	0.0028	0.0035	0.0043	0.0051	0.0063	0.0067	0.0075	0.0080	0.0090	0.0100	
U	0.0010	0.0019	0.0028	0.0031	0.0035	0.0042	0.0055	0.0067	0.0079	0.0088	0.0091	0.0094	0.0110	0.0120	0.0140	
V	0.0015	0.0027	0.0039	0.0045	0.0051	0.0060	0.0079	0.0098	0.0110	0.0122	0.0126	0.0134	0.0160	0.0170	0.0200	
W	0.0019	0.0035	0.0051	0.0059	0.0067	0.0079	0.0102	0.0130	0.0150	0.0165	0.0169	0.0177	0.0190	0.0190	0.0200	
X	0.0022	0.0041	0.0059	0.0071	0.0083	0.0098	0.0130	0.0165	0.0189	0.0210	0.0217	0.0228				
Y	0.0027	0.0049	0.0071	0.0087	0.0102	0.0125	0.0169	0.0217	0.0276	0.0276	0.0276	0.0291				
Z	0.0037	0.0068	0.0098	0.0128	0.0157	0.0210	0.0315	0.0394	0.0433	0.0463	0.0472	0.0472				

How To Use This Chart to Find Cutting Feed Rate (IPR):

1. Find your Alpha Code on the AMG Chart (example: 279 U : U is the Alpha Code)
2. Find the closest diameter for your cutting application on the chart to find your IPR

Application Material Groups (AMG)			Hardness HRC	ISO
1. Steel	1.1 Magnetic soft steel	12L14, 12L15	<120 HB	P 1
	1.2 Structural Steel/ case carburising steel	1005-1025, 1214, 1215, A36	<200 HB	P 1
	1.3 Plain Carbon steel	1030-1060, 1050-1060, 1144-1146	<24	P 2
	1.4 Alloy steel	4140,4340,52100,8620 H11-H41,A2,D2,01,P20,420	<24	P 3
	1.5 Alloy steel/ Hardened and tempered steel	4140,4340,52100,8620 H11-H41,A2,D2,01,P20,420	>24<38	P 4
	1.6 Alloy steel/ Hardened and tempered steel	4140,4340,52100,8620 H11-H41,A2,D2,01,P20,420	>38	H 1
	1.7 Alloy steel Hardened	A2-D2, H10-H41, L1-L6, M1-M42, T1	49-55	H 3
	1.8 Alloy steel Hardened	A2-D2, H10-H41, L1-L6, M1-M42, T1	55-63	H 4
2.Stainless Steel	2.1 Free machining Stainless Steel	200, 303, 416, 420F, 430F, 440	<24	M 1
	2.2 Austenitic	301, 302, 304, 316, 321, 330, CUSTOM 455, AM-350	<24	M 3
	2.3 Ferritic + Austenitic, Martensitic	318-329, 400-446, DUPLEX	<32	M 2
	2.4 Precipitation Hardened	15-5PH, Custom 450 17-4PH	<32	S 2
3.Cast Iron	3.1 Lamellar graphite	Grey, G10, Gg40, J431C, A48 CLASS 20	<150 HB	K 1
	3.2 Lamellar graphite	Grey, GG25-Gg40, J158, A48 CLASS 40-60	>150 HB<32	K 2
	3.3 Nodular graphite/ Malleable Cast Iron	A220, A436, A439, A602, Black, GGG40-GGG70	<200 HB	K 3
	3.4 Nodular graphite/ Malleable Cast Iron	Black Gts/Gtw, J434C	>200 HB<32	K 4
4.Titanium	4.1 Titanium, unalloyed	Commercially Pure	<200 HB	S 1
	4.2 Titanium, alloyed	6Al4V, 6A14V-2Sn, Monel, Monel K	<28	S 2
	4.3 Titanium, alloyed	6Al4V-4Mo, 7A14V-4Mo, 4911-4967	>28<38	S 3
5.Nickel	5.1 Nickel, unalloyed	Commercially Pure, 17644, 200, 5553	<150 HB	S 1
	5.2 Nickel, alloyed	Monel 400, Hastelloy C, Inconel 625, Waspaloy	<28	S 2
	5.3 Nickel, alloyed	Iconel 718,Nimonic 75-95,Rene 41,Iconel 825,A286	>28<38	S 3
6.Copper	6.1 Copper	Commercially Pure	<100 HB	N 3
	6.2 ß-Brass, Bronze	314-340, 350-370	<200 HB	N 4
	6.3 α-Brass	Alloyed Cu + Al + Fe, Long Chipping	<200 HB	N 3
	6.4 High Strength Bronze	Ampco 18-25	<49	N 4
7.Aluminium Magnesium	7.1 Al, Mg, unalloyed	Commercially Pure	<100 HB	N 1
	7.2 Al alloyed, Si<0.5%	6061 T6, 7075, 314-340	<150 HB	N 1
	7.3 Al alloyed, Si>0.5%<10%	6061 T6, 380-390	<120 HB	N 1
	7.4 Al alloyed, Si>10% Mg alloys	Magnesium Whisker Reinforced	<120 HB	N 2
8.Synthetic Materials	8.1 Thermoplastics	Ultramid, Polystrol	---	O
	8.2 Thermosetting plastics	Bakelit, Pertinax	---	O
	8.3 Reinforced plastic materials	CFK, GFKAFK	---	O
9.Hard Mat.	9.1 Cermets (Metal-ceramics)	Ferrotic	<54	H
10.Graphite	10.1 Standard graphite		---	O

JOBBER DRILL

General Purpose Jobber Length Parabolic Flute

Heavy-Duty Parabolic Flute design for efficient chip removal. Allows greater drilling depths in one pass. Low thrust design self centering Split Point for easier penetration.

QC21P Bright Finish improves chip flow in soft or non-ferrous materials.

QC21G TiN Coating increases wear resistance and improves tool life.

	QC21P	QC21G
	ANSI	ANSI
	4XD	4XD
	HSS	HSS
	135°	135°
		
	1/16 - 11/16	1/16 - 1/2

d_1 Ø "/Nr./letter	d_1 decimal Inch	l_2 Inch	l_1 Inch	Pack Qty	QC21P	QC21G
1/16	0.0625	7/8	1.7/8	12	015804	081704
52	0.0635	7/8	1.7/8	12	019452	080552
51	0.0670	1“	2“	12	019451	080551
50	0.0700	1“	2“	12	019450	080550
49	0.0730	1“	2“	12	019449	080549
48	0.0760	1“	2“	12	019448	080548
5/64	0.0781	1“	2“	12	015805	081705
47	0.0785	1“	2“	12	019447	080547
46	0.0810	1.1/8	2.1/8	12	019446	080546
45	0.0820	1.1/8	2.1/8	12	019445	080545
44	0.0860	1.1/8	2.1/8	12	019444	080544
43	0.0890	1.1/4	2.1/4	12	019443	080543
42	0.0935	1.1/4	2.1/4	12	019442	080542
3/32	0.0938	1.1/4	2.1/4	12	015806	081706
41	0.0960	1.3/8	2.3/8	12	019441	080541
40	0.0980	1.3/8	2.3/8	12	019440	080540
39	0.0995	1.3/8	2.3/8	12	019439	080539
38	0.1015	1.7/16	2.1/2	12	019438	080538
37	0.1040	1.7/16	2.1/2	12	019437	080537
36	0.1065	1.7/16	2.1/2	12	019436	080536
7/64	0.1094	1.1/2	2.5/8	12	015807	081707
35	0.1100	1.1/2	2.5/8	12	019435	080535
34	0.1110	1.1/2	2.5/8	12	019434	080534
33	0.1130	1.1/2	2.5/8	12	019433	080533
32	0.1160	1.5/8	2.3/4	12	019432	080532
31	0.1200	1.5/8	2.3/4	12	019431	080531
1/8	0.1250	1.5/8	2.3/4	12	015808	081708
30	0.1285	1.5/8	2.3/4	12	019430	080530
29	0.1360	1.3/4	2.7/8	12	019429	080529
28	0.1405	1.3/4	2.7/8	12	019428	080528
9/64	0.1406	1.3/4	2.7/8	12	015809	081709
27	0.1440	1.7/8	3“	12	019427	080527
26	0.1470	1.7/8	3“	12	019426	080526

JOBBER DRILL

d_1 Ø "/Nr./letter	d_1 decimal Inch	l_2 Inch	l_1 Inch	Pack Qty	QC21P	QC21G
25	0.1495	1.7/8	3“	12	019425	080525
24	0.1520	2“	3.1/8	12	019424	080524
23	0.1540	2“	3.1/8	12	019423	080523
5/32	0.1563	2“	3.1/8	12	015810	081710
22	0.1570	2“	3.1/8	12	019422	080522
21	0.1590	2.1/8	3.1/4	12	019421	080521
20	0.1610	2.1/8	3.1/4	12	019420	080520
19	0.1660	2.1/8	3.1/4	12	019419	080519
18	0.1695	2.1/8	3.1/4	12	019418	080518
11/64	0.1719	2.1/8	3.1/4	12	015811	081711
17	0.1730	2.3/16	3.3/8	12	019417	080517
16	0.1770	2.3/16	3.3/8	12	019416	080516
15	0.1800	2.3/16	3.3/8	12	019415	080515
14	0.1820	2.3/16	3.3/8	12	019414	080514
13	0.1850	2.5/16	3.1/2	12	019413	080513
3/16	0.1875	2.5/16	3.1/2	12	015812	081712
12	0.1890	2.5/16	3.1/2	12	019412	080512
11	0.1910	2.5/16	3.1/2	12	019411	080511
10	0.1935	2.7/16	3.5/8	12	019410	080510
9	0.1960	2.7/16	3.5/8	12	019409	080509
8	0.1990	2.7/16	3.5/8	12	019408	080508
7	0.2010	2.7/16	3.5/8	12	019407	080507
13/64	0.2031	2.7/16	3.5/8	12	015813	081713
6	0.2040	2.1/2	3.3/4	12	019406	080506
5	0.2055	2.1/2	3.3/4	12	019405	080505
4	0.2090	2.1/2	3.3/4	12	019404	080504
3	0.2130	2.1/2	3.3/4	12	019403	080503
7/32	0.2188	2.1/2	3.3/4	12	015814	081714
2	0.2210	2.5/8	3.7/8	12	019402	080502
1	0.2280	2.5/8	3.7/8	12	019401	080501
A	0.2340	2.5/8	3.7/8	12	019301	—
15/64	0.2344	2.5/8	3.7/8	12	015815	081715
B	0.2374	2.3/4	4“	12	019302	—
C	0.2421	2.3/4	4“	12	019303	—
D	0.2461	2.3/4	4“	12	019304	—
1/4	0.2500	2.3/4	4“	12	015816	081716
F	0.2571	2.7/8	4.1/8	12	019306	—
G	0.2610	2.7/8	4.1/8	12	019307	—
17/64	0.2656	2.7/8	4.1/8	12	015817	081717
H	0.2661	2.7/8	4.1/8	12	019308	—
I	0.2720	2.7/8	4.1/8	12	019309	—
J	0.2772	2.7/8	4.1/8	12	019310	—
K	0.2811	2.15/16	4.1/4	12	019311	—
9/32	0.2813	2.15/16	4.1/4	12	015818	081718
L	0.2902	2.15/16	4.1/4	12	019312	—
M	0.2949	3.1/16	4.3/8	12	019313	—
19/64	0.2969	3.1/16	4.3/8	12	015819	081719
N	0.3020	3.1/16	4.3/8	12	019314	—
5/16	0.3125	3.3/16	4.1/2	6	015820	081720
O	0.3161	3.3/16	4.1/2	6	019315	—
P	0.3228	3.5/16	4.5/8	6	019316	—
21/64	0.3281	3.5/16	4.5/8	6	015821	081721
Q	0.3319	3.7/16	4.3/4	6	019317	—
R	0.3390	3.7/16	4.3/4	6	019318	—
11/32	0.3437	3.7/16	4.3/4	6	015822	081722
S	0.3480	3.1/2	4.7/8	6	019319	—
T	0.3580	3.1/2	4.7/8	6	019320	—
23/64	0.3594	3.1/2	4.7/8	6	015823	081723
U	0.3680	3.5/8	5“	6	019321	—
3/8	0.3750	3.5/8	5“	6	015824	081724
V	0.3772	3.5/8	5“	6	019322	—
W	0.3858	3.3/4	5.1/8	6	019323	—
25/64	0.3906	3.3/4	5.1/8	6	015825	081725
X	0.3969	3.3/4	5.1/8	6	019324	—
Y	0.4039	3.7/8	5.1/4	6	019325	—
13/32	0.4063	3.7/8	5.1/4	6	015826	081726

JOBBER DRILL

d_1 Ø “/Nr./letter	d_1 decimal Inch	l_2 Inch	l_1 Inch	Pack Qty	QC21P	QC21G
Z	0.4130	3.7/8	5.1/4	6	019326	—
27/64	0.4219	3.15/16	5.3/8	6	015827	081727
7/16	0.4375	4.1/16	5.1/2	6	015828	081728
29/64	0.4531	4.3/16	5.5/8	6	015829	081729
15/32	0.4687	4.5/16	5.3/4	6	015830	081730
31/64	0.4844	4.3/8	5.7/8	6	015831	081731
1/2	0.5000	4.1/2	6“	6	015832	081732
33/64	0.5156	4.13/16	6.5/8	1	015833	—
17/32	0.5313	4.13/16	6.5/8	1	015834	—
35/64	0.5469	4.13/16	6.5/8	1	015835	—
9/16	0.5625	4.13/16	6.5/8	1	015836	—
37/64	0.5781	4.13/16	6.5/8	1	015837	—
19/32	0.5937	5.3/16	7.1/8	1	015838	—
39/64	0.6094	5.3/16	7.1/8	1	015839	—
5/8	0.6250	5.3/16	7.1/8	1	015840	—
41/64	0.6406	5.3/16	7.1/8	1	015841	—
21/32	0.6563	5.3/16	7.1/8	1	015842	—
43/64	0.6719	5.5/8	7.5/8	1	015843	—
11/16	0.6875	5.5/8	7.5/8	1	015844	—