




# FALL PROTECTION

## WELDING HIGH HEAT HARNESS



### KEVLAR® WEBBING

Excellent for high heat and char resistance



### QUICK CONNECT CHEST BUCKLE

Provides fast and easy connections



### NOMEX STRAP KEEPERS

Keeps excess webbing organized and out of the way



### D RING

Adjustable for optimal fit on different body sizes



### LABEL PROTECTION

Durable cover easily reveals labels



### IMPACT INDICATOR

Clearly shows if the harness has been involved in a fall

## WELDING/HIGH HEAT HARNESS



### Standard Harness

For fall arrest only, features only a dorsal D-Ring on the back.

#### SMALL

H913001 Quick Connect Legs

#### MEDIUM/LARGE

H913002 Quick Connect Legs

#### X-LARGE

H913004 Quick Connect Legs

#### XX-LARGE

H913005 Quick Connect Legs

### Welding High Heat Performance

- Whole Harness of Kevlar Web
  - Resists 700°F Char Temperature
- Nomex Strap Keepers
- ANSI z359.11 Compliance

### Proven Post-Fall Performance

- Patented Relief Handles
- Built in Suspension Trauma Relief
- Offsetting color for visibility
- Easy to grab handle to assist post-fall positioning

### Comfort and Fit

- Quick Connect Chest and Legs
- Quick Hip Adjustment

PATENT PENDING

## RELIEF HANDLE

POST-FALL ADJUSTMENT SYSTEM



Achieve gravity override in seconds, relieving the pressure on femoral arteries.

Welding/High Heat Harnesses can be utilized with Werner Arc Flash connecting devices. Please contact Customer Care for more information.



[www.wernerco.com](http://www.wernerco.com)

WERNERCO CORPORATE HEADQUARTERS: 93 Werner Rd., Greenville, PA 16125-9499  
TEL: (724) 588-8600 FAX: (724) 588-0315 [www.wernerladder.com](http://www.wernerladder.com)